

## **LIST OF FIGURES**

- Figure C-1 Key to Symbols Used on Figures.
- Figure C-2 Location of Support Services Area, Lawrence Berkeley National Laboratory.
- Figure C-3 SWMUs, AOCs and Other Investigation Areas in the Support Services Area Discussed in Module C.
- Figure C2.1-1 Stratigraphic Correlation Chart, Lawrence Berkeley National Laboratory.
- Figure C2.1-2 Bedrock Geologic Map, Lawrence Berkeley National Laboratory.
- Figure C2.1-3 Surficial Geologic Map (modified from Harding-Lawson Associates, 1982), Lawrence Berkeley National Laboratory.
- Figure C2.2-1 Pre-Development (1956) Topography of Support Services Area (modified from Hammon, Jensen, and Wallen, 1956).
- Figure C2.2-2 LBNL Surface Hydrology and Stormwater Drainage System.
- Figure C2.2-3 Topography of Support Services Area.
- Figure C2.2-4 Support Services Area Storm Drainage System.
- Figure C2.2-5 Hydraugers and Subdrains in the Support Services Area.
- Figure C2.3-1 Support Services Area Bedrock Geologic Map.
- Figure C2.3-2 Support Services Area Cross Section A–A'.
- Figure C2.3-3 Support Services Area Cross Section B–B'.
- Figure C2.3-4 Support Services Area Cross Section C–C'.
- Figure C2.3-5 Support Services Area Cross Section D–D'.
- Figure C2.3-6 Support Services Area Cross Section E–E'.
- Figure C2.3-7 Support Services Area Cross Section F–F'.
- Figure C2.3-8 Support Services Area Cross Section G–G'.
- Figure C2.4-1 Support Services Area Well Locations Showing Hydraulic Conductivity Estimates Calculated From Slug Tests and Pumping Tests.
- Figure C2.4-2 Water Level Elevation Contour Map, Support Services Area, Fourth Quarter Fiscal Year 1999.
- Figure C2.4-3 Hydrograph of Well MW91-4.
- Figure C2.4-4 Hydrograph of Well MW75-99-7.
- Figure C2.4-5 Hydrograph of Well MW75-96-20.
- Figure C2.4-6 Stiff Diagram of Groundwater Geochemical Parameters in Areas 3, 4, and 5.
- Figure C3.1-1 Building 75 Former HWHF (SWMU 3-6), Soil Boring and Cross Section Locations.

- Figure C3.1-2 Concentrations of PCBs Detected in Soil Samples (mg/kg) from 0 to 2.0 feet bgs, Building 75 Former HWHF (SWMU 3-6).
- Figure C3.1-3 Concentrations of PCBs Detected in Soil Samples (mg/kg) from 2.2 to 3.8 feet bgs, Building 75 Former HWHF (SWMU 3-6).
- Figure C3.1-4 Concentrations of PCBs Detected in Soil Samples (mg/kg) from 4.0 to 6.8 feet bgs, Building 75 Former HWHF (SWMU 3-6).
- Figure C3.1-5 Concentrations of PCBs Detected in Soil Samples (mg/kg) from 7.3 to 11.0 feet bgs, Building 75 Former HWHF (SWMU 3-6).
- Figure C3.1-6 Concentrations of PCBs Detected in Soil Samples (mg/kg) from 12.1 to 17.8 feet bgs, Building 75 Former HWHF (SWMU 3-6).
- Figure C3.1-7 Cross Section A-A' Showing Concentrations of PCBs Detected (mg/kg), Building 75 Former HWHF (SWMU 3-6).
- Figure C3.1-8 Cross Section B-B' Showing Concentrations of PCBs Detected (mg/kg), Building 75 Former HWHF (SWMU 3-6).
- Figure C3.1-9 Cross Section C-C' Showing Concentrations of PCBs Detected (mg/kg), Building 75 Former HWHF (SWMU 3-6).
- Figure C3.1-10 Hydrocarbons (TPH) in the Range of Crude/Waste Oil in Soil, Building 75 Former Hazardous Waste Handling Facility (SWMU 3-6).
- Figure C3.1-11 Non-Aromatic Halogenated VOCs and Acetone Detected in Soil, Building 75 Former Hazardous Waste Handling Facility.
- Figure C3.1-12 Aromatic VOCs in Soil, Building 75 Former Hazardous Waste Handling Facility.
- Figure C3.1-13 SVOCs in Soil, Building 75 Former Hazardous Waste Handling Facility (SWMU 3-6).
- Figure C3.1-14 Metals Exceeding Background and PRGs in Soil, Building 75 Former Hazardous Waste Handling Facility (SWMU 3-6).
- Figure C3.2-1 Locations of Soil Borings and Maximum Concentrations of Analytes Detected Above Background Levels (mg/kg), Building 76 Motor Pool Collection Trenches (SWMU 4-3).
- Figure C3.3-1 Locations of Soil Borings and Maximum Concentrations of Contaminants Detected (mg/kg), Building 77 Plating Shop (SWMU 5-4).
- Figure C3.4-1 Soil Sample Locations Showing Detected Total Petroleum Hydrocarbons and Fuel-Related Aromatic VOCs Exceeding PRGs, Building 76 Motor Pool Area and the Former Gasoline and Diesel USTs (AOCs 4-1 and 4-2).
- Figure C3.4-2 Geologic Cross-Section A-A' Showing Total Petroleum Hydrocarbon Concentrations (mg/kg), Building 76 Motor Pool Area (AOCs 4-1 and 4.2).
- Figure C3.4-3 Geologic Cross-Section B-B' Showing Total Petroleum Hydrocarbon Concentrations (mg/kg), Building 76 Motor Pool Area (AOCs 4-1 and 4.2).

- Figure C3.5-1 Site Map, Building 77 Sanitary Sewer System (AOC 5-4) and Related Sampling Locations Showing Detected Contaminant Concentrations (mg/kg).
- Figure C3.6-1 Locations of Soil Samples and Concentrations of Contaminants Detected (mg/kg), Chicken Creek Poultry Research Station.
- Figure C3.7-1 Locations of Soil Samples and Concentrations of Contaminants Detected (mg/kg), Reported by Pacific Gas and Electric (PG&E) 1994, Grizzly Substation.
- Figure C3.7-2 Locations of Soil Samples Collected in 1998 and Concentrations of Contaminants Detected (mg/kg), Grizzly Substation.
- Figure C3.8-1 Other Locations of Soil Samples, Support Services Area.
- Figure C4.1-1 Areas of Groundwater Contamination (Halogenated VOCs) in the Support Services Area (Fiscal Year 1999) with Groundwater AOCs Shown.
- Figure C4.2-1 Generalized Degradation Pathways of Chlorinated Hydrocarbons.
- Figure C4.3-1 Isoconcentration Contour Map: Mean Concentrations of Total Halogenated Non-Aromatic VOCs Near Water Table, Support Services Area, Fiscal Year 1999.
- Figure C4.3-2 Isoconcentration Contour Map: Mean Concentrations of PCE Near Water Table, Support Services Area, Fiscal Year 1999.
- Figure C4.3-3 Isoconcentration Contour Map: Mean Concentrations of TCE Near Water Table, Support Services Area, Fiscal Year 1999.
- Figure C4.3-4 Isoconcentration Contour Map: Mean Concentrations of cis-1,2-DCE Near Water Table, Support Services Area, Fiscal Year 1999.
- Figure C4.3-5 Isoconcentration Contour Map: Mean Concentrations of trans-1,2-DCE Near Water Table, Support Services Area, Fiscal Year 1999.
- Figure C4.3-6 Isoconcentration Contour Map: Mean Concentrations of 1,1-DCE Near Water Table, Support Services Area, Fiscal Year 1999.
- Figure C4.3-7 Isoconcentration Contour Map: Mean Concentrations of 1,1,1-TCA Near Water Table, Support Services Area, Fiscal Year 1999.
- Figure C4.3-8 Isoconcentration Contour Map: Mean Concentrations of 1,1-DCA Near Water Table, Support Services Area, Fiscal Year 1999.
- Figure C4.3-9 Isoconcentration Contour Map: Mean Concentrations of Vinyl Chloride Near Water Table, Support Services Area, Fiscal Year 1999.
- Figure C4.3-10 Isoconcentration Contour Map: Mean Concentrations of Chloroform Near Water Table, Support Services Area, Fiscal Year 1999.
- Figure C4.3-11 Cross Section Index Map of the Support Services Area.
- Figure C4.3-12 Support Services Area Hydrogeologic Cross Section B-B'.

- Figure C4.3-13 Support Services Area Hydrogeologic Cross Section F-F'.
- Figure C4.3-14 Concentrations of Total Halogenated VOCs in Wells Located in the Support Services Area.
- Figure C4.3-15 Isoconcentration Contour Map (Plume Map): Mean Concentrations of Total Halogenated Non-Aromatic VOCs (FY1999) in Support Services Area, With Potential Source Areas (SWMUs and AOCs) for the Groundwater Contamination.
- Figure C4.4-1 Wells Where TPH Has Been Detected in Groundwater in the Support Services Area, With Locations of SWMUs and AOCs That Stored or Used Fuel Products or Other Hydrocarbon-Based Products.
- Figure C4.4-2 Wells Where the Same Aromatic Hydrocarbon Has Been Detected in Groundwater More Than One Sampling Event in the Support Services Area, With Locations of SWMUs and AOCs That Stored or Used Fuel Products or Other Hydrocarbon-Based Products.
- Figure C4.4-3 Locations of Well Sampled for SVOCs in the Support Services Area, With Locations of SWMUs and AOCs That Stored or Used SVOCs.
- Figure C4.4-4 Locations of Wells Sampled for PCBs in the Support Services Area, With Locations of PCBs Detected in Soil and SWMUs and AOCs That Stored or Used PCBs.
- Figure C4.4-5 Maximum Concentrations of Metals Detected in Groundwater Above MCLs During More Than One Quarter in the Support Services Area.
- Figure C4.5-1 Surface Water Sampling Locations Evaluating Potential Migration Pathways of Contamination in Support Services Area to Surface Water.
- Figure C4.5-2 Sediment Sampling Locations Evaluating Potential Migration Pathways of Contamination in Support Services Area to Surface Water.
- Figure C5.1-1 Indoor Air Sampling Locations, Support Services Area.

|   |            |  |   |  |
|---|------------|--|---|--|
| T | SB16-94-11 | Temporary groundwater sampling point   | LT  | Less than reporting limit                    |
|   | MW76-93-7  | Groundwater monitoring well  | ND (or <)   | Not detected                                 |
|   | SB76-94-01 | Soil boring  | NS  | Not sampled                                  |
|   | SB76-94-04 | Angled soil boring   | NA  | Not analyzed                                 |
|   | SS51-97-1  | Shallow soil sample location   |   |  |
|   | SG-76W-7   | Soil-gas probe   | 17  | Surface structure<br>(e.g., buildings, etc.) |
| □ |            | Shallow soil-gas sampling location   | A ————— A'  | Cross section                                |
|   | 7-95-1     | Soil-gas monitoring well   |             | Sanitary sewer line                          |
| ◇ | VZM-OT-1   | Vadose zone monitoring well  |             | Abandoned sanitary sewer                     |
| ▽ | L-3        | Vacuum lysimeter   |           | Storm drain line                             |
| P | PZ 51-92-3 | Piezometer   |           | LBNL site boundary                           |
| ○ | SSW-C.63   | Slope stability well   |  750      | Water level elevation contour line<br>(feet) |
| ⊕ | SI-8.107   | Slope indicator well   |  900      | Topographic contour line (feet)              |
| ○ | EW 7B-96-1 | Extraction well  |  51-01-09 | Hydrauger                                    |
| T | SB16-94-11 | Properly destroyed groundwater monitoring well or temporary groundwater sampling point | ▲   | Solid Waste Management Unit                  |
|   | MW76-93-7  |  | ▲   | Area of Concern                              |
| ● | ☒          | Soil sampling location (in soil borings)   |   |  |
|   | ☒          | Sample location was excavated  |   |  |

NOTE: Other symbols used are explained on the figures.

**Figure C-1. Key to Symbols Used on Figures.**





Figure C-2. Location of the Support Services Area, Lawrence Berkeley National Laboratory.



**Figure C-3. Locations of SWMUs, AOCs, and Other Investigation Areas in the Support Services Area Discussed in Module C.**

| <b>Age</b> | <b>Formation</b> | <b>Description</b>  |
|------------|------------------|---|
| Quaternary | Artificial fill  | Generally engineered fill consisting of fine-grained material. Older fills include vegetative and other debris. |
|            | Colluvium        | Predominantly clayey silt.  |
|            | Debris flows     | Boulders and gravels of basalt, chert, and porcelenite in a silty clay matrix.                                  |
|            | Landslides       | Translational/rotational slide masses incorporating bedrock. Occur at the Moraga/Orinda Formation contact.      |

| <b>Age</b> | <b>WEST OF HAYWARD FAULT</b> | <b>EAST OF HAYWARD FAULT</b>                                    |                  |   |   |                  |   |
|------------|------------------------------|---|------------------|---|---|------------------|---|
|            |                              | <i>West of Life Sciences Area Main Canyon Landslide Deposit</i> |                  |   | <i>East of Life Sciences Area Main Canyon Landslide Deposit</i> |                  |   |
|            |                              | <b>Group</b>  | <b>Formation</b> | <b>Description</b>  | <b>Group</b>  | <b>Formation</b> | <b>Description</b>  |
| Tertiary   |                              | Contra Costa  | Moraga           | Andesitic flows, breccias, and agglomerates with minor amounts of basaltic flows and interbedded volcanoclastic sandstone and conglomerate. | San Pablo (?)   | Neroly           | Fossiliferous, shallow marine, fine grained sandstones with minor amounts of siltstone. |
|            |                              |   | Orinda           | Alluvial sedimentary deposits consisting primarily of claystone and siltstone with lenticular to linear beds of sandstone and conglomerate. |   | Briones          | Fossiliferous, shallow marine, fine grained sandstones with minor amounts of siltstone. |
| Cretaceous |                              | Great Valley  |                  | Marine mudstones, shales, and sandstones.   | Monterey  | Claremont        | Chert and shale with minor amounts of sandstone.  |
| Jurassic   | Franciscan Complex           |   |                  |   |   |                  |   |

**Figure C2.1-1. Stratigraphic Correlation Chart, Lawrence Berkeley National Laboratory.**




Figure C2.1-2. Bedrock Geologic Map, Lawrence Berkeley National Laboratory.





Figure C2.1-3 Surficial Geologic Map (modified from Harding-Lawson Associates, 1982).

C2.1-3 site surf map.ai  
09/00



**Figure C2.2-1. Pre-Development (1956) Topography of Support Services Area  
(modified from Hammon, Jensen, and Wallen, 1956).**

C2.2-1.lai  
09/00




Figure C2.2-2. LBNL Surface Hydrology and Stormwater Drainage System.




Figure C2.2-3. Topography of Support Services Area.




Figure C2.2-4. Support Services Area Storm Drainage System.





Figure C2.2-5. Hydraugers and Subdrains in the Support Services Area.



|                 |   |
|-----------------|---|
| <b>QTIs(m)</b>  | Paleolandslide Deposit Composed of Moraga Formation Rocks |
| <b>QTIs(mo)</b> | Paleolandslide Deposit (Mixed Unit)                       |
| <b>Tm</b>       | Moraga Formation  |
| <b>To</b>       | Orinda Formation  |
| <b>Tsp</b>      | San Pablo Group   |
| <b>Tc</b>       | Claremont Formation                                       |
| <b>Kgv</b>      | Great Valley Group  |
| <b>JKf</b>      | Franciscan Complex  |

tinted box indicates unit appears in figure

#### Support Services area cross section

Boundary of Lawrence Berkeley National Laboratory

Environmental monitoring wells includes groundwater and soil gas wells and lysimeters

Soil borings includes slope indicators and slope stability wells

Historic springs (modified from Soule, 1875)

75  
Contact, showing dip dashed where approximately located; dotted where concealed by other map units

35  
Fault, showing dip dashed where approximately located; dotted where concealed; queried where inferred

60  
Strike and dip of beds

APPROXIMATE MEAN DECLINATION, 2000

revision: 9/26/2000

**Figure C2.3-1. Support Services Area Bedrock Geologic Map.**

C2.3-1 br map.ai  
09/00




Figure C2.3-2 . Support Services Area Cross Section A-A'.





Figure C2.3-3. Support Services Area Cross Section B-B'.





Figure C2.3-4. Support Services Area Cross Section C-C'.








Figure C2.3-5. Support Services Area Cross Section D-D'.


C2.3-5 sec d.ai  
09/00



**Figure C2.3-6. Support Services Area Cross Section E-E'.**



**Figure C2.3-7. Support Services Area Cross Section F-F'.**






Figure C2.4-1. Support Services Area Well Locations Showing Hydraulic Conductivity Estimates Calculated from Slug Tests and Pumping Tests.




Figure C2.4-2. Water Level Elevation Contour Map, Support Services Area, Fourth Quarter Fiscal Year 1999.




Figure C2.4-3. Hydrograph of Well MW91-4.




Figure C2.4-4. Hydrograph of Well MW75-99-7.




Figure C2.4-5. Hydrograph of Well MW75-96-20.





Figure C2.4-6. Stiff Diagrams of Groundwater Geochemical Parameters in Support Services Area.


### Explanation

10-Foot soil sample grid lines

See Figure C-1 for Key to Symbols



APPROXIMATE MEAN DECLINATION, 2000



Subsurface telephone  
and electrical vaults

B

C

J Pad

### Key To Sample Locations

- A1 Soil Borings SB75AHW-97-1 through -15 and SB75A-97-3 and -12, in Building 75A.
- E1 Soil Borings SB75EHW-97-1 through -3, in Building 75 Room 131E.
- FL1 Soil Borings SB75FLHW-97-1 through -4, upslope of fence line between HWHF and tritium stack.
- J1 Soil Borings SB75JHW-97-1 and -2 and SB75J-97-3, on Storage Pad (75j).
- LY1 Soil Borings SB75LYHW-97-1 through -6, on paved area (alley) between Building 75 and Building 75A.
- Y1 Soil Borings SB75YHW-97-1 through -8, in HWHF Yard.
- Y97-1 Soil Borings SB75Y-97-1, -2A, -3A, -4, -5, -9, and -10, in HWHF Yard.
- SB1 Soil borings SB75YSWR-97-1 and -2, adjacent to sanitary sewer.
- 96-1 Soil borings SB75-96-1 through -4, east and south of Building 75A converted to lysimeter.
- A96-1 Angled soil boring, SB75A-96-1, north of Building 75A.
- 98-1 Soil borings, SB75A-98-1 and -2, near southeast corner of Building 75A.
- 99-1 Soil borings SB75A-99-1 through -37 and SB75-99-27A, -37A, and -37B, drilled for characterization of PCBs.






Figure C3.1-1. Building 75 Former HWHF (SWMU 3-6), Soil Boring and Cross Section Locations.





**Figure C3.1-3. Concentrations of PCBs Detected in Soil Samples (mg/kg) from 2.2 to 3.8 feet bgs, Building 75 Former HWHF (SWMU 3-6).**






Figure C3.1-4. Concentrations of PCBs Detected in Soil Samples (mg/kg) from 4.0 to 6.8 feet bgs, Building 75 Former HWHF (SWMU 3-6).





**Figure C3.1-6. Concentrations of PCBs Detected in Soil Samples (mg/kg) from 12.1 to 17.8 feet bgs, Building 75 Former HWHF (SWMU 3-6).**




Figure C3.1-7. Cross Section A-A' Showing Concentrations of PCBs Detected (mg/kg), Building 75 Former HWHF (SWMU 3-6).




Figure C3.1-8. Cross Section B-B' Showing Concentrations of PCBs Detected (mg/kg), Building 75 Former HWHF (SWMU 3-6).




Figure C3.1-9. Cross Section C-C' Showing Concentrations of PCBs Detected (mg/kg), Building 75 Former HWHF (SWMU 3-6).

### Explanation

*Concentration of TPH-C/WO in Soil*

**ND** Soil sample(s) with no TPH-C/WO detected

**27** Soil boring(s) with TPH-C/WO detected,  
showing maximum concentration (mg/kg)

Note: Figure only includes borings sampled for TPH

See Figure C-1 for Key to Symbols




Figure C3.1-10. Hydrocarbons (TPH) in the Range of Crude/Waste Oil Detected in Soil, Building 75 Former Hazardous Waste Handling Facility (SWMU 3-6).

### Explanation

Concentration of TPH-C/WO in Soil

**ND** VOCs/Acetone not detected

**27** VOCs/Acetone detected,  
showing maximum concentration (mg/kg)

Note: Figure only includes borings sampled for VOCs/Acetone

See Figure C-1 for Key to Symbols



Figure C3.1-11. Non-Aromatic Halogenated VOCs and Acetone Detected in Soil, Building 75 Former Hazardous Waste Handling Facility. 09/00

### Explanation


*Concentration of Aromatic VOCs in Soil*

ND Aromatic VOCs not detected

Toluene 27 Toluene detected,  
showing maximum concentration (mg/kg)

Note: Figure only includes borings sampled for Aromatic VOCs

See Figure C-1 for Key to Symbols



APPROXIMATE MEAN DECLINATION, 2000

0 10 20 40  
SCALE (feet)




Figure C3.1-12. Aromatic VOCs in Soil, Building 75 Former Hazardous Waste Handling Facility.

### Explanation

Concentration of SVOCs in Soil

ND SVOCs not detected

**benzyl alcohol 0.32** Benzyl alcohol detected, showing maximum concentration (mg/kg)

Note: Figure only includes borings sampled for SVOCs

See Figure C-1 for Key to Symbols




Figure C3.1-13. SVOCs in Soil, Building 75 Former Hazardous Waste Handling Facility (SWMU 3-6).

### Explanation

#### Concentration of Metals in Soil

ND metals not detected

Ni 217 Nickel detected,  
showing maximum concentration (mg/kg)

Note: Figure only includes borings sampled for metals

See Figure C-1 for Key to Symbols







Figure C3.1-14. Metals Exceeding Background and PRGs in Soil, Building 75 Former Hazardous Waste Handling Facility (SWMU 3-6).




**Figure C3.2-1. Locations of Soil Borings and Maximum Concentrations of Analytes Detected Above Background Levels (mg/kg), Building 76 Motor Pool Collection Trenches (SWMU 4-3).**



**Figure C3.3-1. Locations of Soil Borings and Maximum Concentrations of Contaminants Detected (mg/kg), Building 77 Plating Shop (SWMU 5-4).**





**Figure C3.4-2. Geologic Cross-Section A-A' Showing Total Petroleum Hydrocarbon Concentrations (mg/kg), Building 76 Motor Pool Area (AOCs 4-1 and 4.2).**

C3.4-2AA.ai  
09/00




Figure C3.4-3. Geologic Cross-Section B-B' Showing Total Petroleum Hydrocarbon Concentrations, Building 76 Motor Pool Area (AOCs 4-1 and 4-2).






Figure C3.5-1. Site Map, Building 77 Sanitary Sewer System (AOC 5-4) and Related Sampling Locations Showing Detected Contaminant Concentrations (mg/kg).




#### Explanation

● Soil sample location  
 CKPit-97-2  
 4,4-DDE=0.0003 Analytical results, in mg.kg  
 4,4-DDT=0.0003



0 5 10 ft  
Scale



See Figure C-1 for Key to Symbols

Figure C3.6-1. Locations of Soil Samples and Concentrations of Contaminants Detected (mg/kg),  
Chicken Creek Poultry Research Station.




Figure C3.7-1. Locations of Soil Samples and Concentrations of Contaminants Detected (mg/kg), Reported by Pacific Gas and Electric (PG&E) 1994, Grizzly Substation.




Figure C3.7-2. Locations of Soil Samples Collected in 1998 and Concentrations of Contaminants Detected (mg/kg), Grizzly Substation.










Figure C3.8-1. Other Locations of Soil Samples, Support Services Area.




**Figure C4.1-1. Areas of Groundwater Contamination (Halogenated VOCs) in the Support Services Area (Fiscal Year 1999) with Groundwater AOCs Shown.**




Modified from McCarty (1994) and Nyer and Duffin (1997)


Figure C4.2-1. Generalized Degradation Pathways of Chlorinated Hydrocarbons.




**Figure C4.3-1. Isoconcentration Contour Map: Mean Concentrations of Total Halogenated Non-Aromatic VOCs Near Water Table, Support Services Area, Fiscal Year 1999.**




**Figure C4.3-2. Isoconcentration Contour Map: Mean Concentrations of PCE Near Water Table, Support Services Area, Fiscal Year 1999.**




**Figure C4.3-3. Isoconcentration Contour Map: Mean Concentrations of TCE Near Water Table, Support Services Area, Fiscal Year 1999.**




**Figure C4.3-4. Isoconcentration Contour Map: Mean Concentrations of cis-1,2-DCE Near Water Table, Support Services Area, Fiscal Year 1999.**




**Figure C4.3-5. Isoconcentration Contour Map: Mean Concentrations of trans-1,2-DCE Near Water Table, Support Services Area, Fiscal Year 1999.**




**Figure C4.3-6. Isoconcentration Contour Map: Mean Concentrations of 1,1-DCE Near Water Table, Support Services Area, Fiscal Year 1999.**




**Figure C4.3-7. Isoconcentration Contour Map: Mean Concentrations of 1,1,1-TCA Near Water Table, Support Services Area, Fiscal Year 1999.**



**Figure C4.3-8. Isoconcentration Contour Map: Mean Concentrations of 1,1-DCA Near Water Table, Support Services Area, Fiscal Year 1999.**



**Figure C4.3-9. Isoconcentration Contour Map: Mean Concentrations of Vinyl Chloride Near Water Table, Support Services Area, Fiscal Year 1999.**



**Figure C4.3-10. Isoconcentration Contour Map: Mean Concentrations of Chloroform Near Water Table, Support Services Area, Fiscal Year 1999.**








Figure C4.3-11. Cross Section Index Map of the Support Services Area.



**Figure C4.3-12. Support Services Area Hydrogeologic Cross Section B-B'.**

revision 9/29/2000

C4.3-12SSAreaBB'.ai  
09/00



**Figure C4.3-13. Support Services Area Hydrogeologic Cross Section F-F'.**







Figure C4.3-14. Concentrations of Total Halogenated VOCs in Wells Located in the Support Services Area.




**Figure C4.3-15. Isoconcentration Contour Map: Mean Concentrations of Total Halogenated Non-Aromatic VOCs (FY1999) in Support Services Area, With Potential Source Areas (SWMUs and AOCs) for the Groundwater Contamination.**




**Figure C4.4-1. Wells Where TPH Has Been Detected in Groundwater in the Support Services Area, With Locations of SWMUs and AOCs That Stored or Used Fuel Products or Other Hydrocarbon-Based Products.**




**Figure C4.4-2. Wells Where the Same Aromatic Hydrocarbon Has Been Detected in Groundwater More Than One Sampling Event in the Support Services Area, With Locations of SWMUs and AOCs That Stored or Used Fuel Products or Other Hydrocarbon-Based Products.**



**Figure C4.4-3. Locations of Wells Sampled for SVOCs in the Support Services Area With Locations of SWMUs and AOCs That Stored or Used SVOCs.**



**Figure C4.4-4. Locations of Wells Sampled for PCBs in the Support Services Area With Locations of PCBs Detected in Soil and SWMUs and AOCs That Stored or Used PCBs.**



**Figure C4.4-5. Maximum Concentrations of Metals Detected in Groundwater Above MCLs During More Than One Quarter in the Support Services Area.**




Figure C4.5-1.

Surface Water Sampling Locations Evaluating Potential Migration Pathways of Contamination in Support Services Area to Surface Water.

C4.5-1SSAreaSurfWtr.ai  
09/00




Figure C4.5-2.

Sediment Sampling Locations Evaluating Potential Migration Pathways of Contamination in Support Services Area to Surface Water.




Figure C5.1-1. Indoor Air Sampling Locations, Support Services Area.